

HAER  
NY  
3-BRONX  
16-

## HISTORIC AMERICAN ENGINEERING RECORD

### INDEX TO PHOTOGRAPHS

#### **SHEFFIELD FARMS MILK PLANT**

HAER NO. NY-267

1075 Webster Avenue  
(southwest corner of 166th Street)  
Bronx  
Bronx County  
New York

Photographer: Richard D. Pieper for Perkins Geddis Eastman Architects  
June 1991

- |           |   |
|-----------|---|
| NY-267-1  | 3/4 view, looking southwest on Webster Avenue   |
| NY-267-2  | View north, east front of complex   |
| NY-267-3  | View northwest, east front to the right and adjacent 1923 annex to the left           |
| NY-267-4  | View west, east front   |
| NY-267-5  | View southwest, east front of 1923 annex  |
| NY-267-6  | View southeast, north side  |
| NY-267-7  | Detail of 3rd floor parapet, cornice and window bay                                   |
| NY-267-8  | Detail of typical ground floor arch   |
| NY-267-9  | Detail of typical terra cotta cowhead   |
| NY-267-10 | Detail of typical milk bottle keystone  |
| NY-267-11 | Roof, view south, center stair bulkhead and chimney stack                             |
| NY-267-12 | Roof, view south, atrium structure and chimney stack                                  |
| NY-267-13 | 4th Floor roof, view east, south elevation detail of setback including steel platform |
| NY-267-14 | 4th floor roof, view southeast, parapet and office stair bulkhead                     |
| NY-267-15 | 4th floor roof, view north, east front of setback to left and parapet to right        |

Index to Photographs  
Sheffield Farms Milk Plant  
HAER No. NY-267 (Page 2)

NY-267-16	4th floor roof, view west, north side of setback to left and delivery stair bulkhead to right
NY-267-17	4th floor roof, view south, 4th and 5th floor setback to left and atrium structure to right
NY-267-18	Second floor, milk room looking south, overall view
NY-267-19	Fourth floor, top level of milk room looking north
NY-267-20	Fourth floor, top level of milk room looking south (original location of clarifiers)
NY-267-21	Fourth floor, second level of milk room looking southeast (original location of heaters)
NY-267-22	Fourth floor, second level of milk room looking northeast
NY-267-23	Third floor, third level of milk room, looking southwest at existing dairy equipment (original location of pasteurizing holding cylinders)
NY-267-24	Second floor, milk room looking at existing mechanical equipment
NY-267-25	Fifth floor, northeast corner, looking north
NY-267-26	Fifth floor, southeast corner, looking south
NY-267-27	Fifth floor, looking north at original milk dumping and milk-storage tank room
NY-267-28	Fifth floor, southwest corner, looking west into top of spiral stair

Index to Photographs  
Sheffield Farms Milk Plant  
HAER No. NY-267 (Page 3)

NY-267-29	Fifth floor, detail of original "main switch" electrical panel
NY-267-30	Fourth floor, looking northeast at former milk-storage tank room
NY-267-31	Fourth floor, looking south at former milk-storage tank room, spiral stair in right hand corner
NY-267-32	Fourth floor, southwest corner, looking west at spiral stair
NY-267-33	Third floor, looking north, elevator and central stair to the right (original ice manufacturing floor)
NY-267-34	Third floor, looking northwest at elevator and central stair
NY-267-35	Third floor, detail of elevator
NY-267-36	Third floor, north half of floor, looking north showing offset structural beams
NY-267-37	Third floor, north half of floor, looking northwest
NY-267-38	Third floor, south half of floor, looking south
NY-267-39	Third floor, south half of floor, looking west at fire stair and stair to milk room
NY-267-40	Third floor - looking northeast with elevator and central stair at center
NY-267-41	Third floor, north half of floor, looking northeast
NY-267-42	Third floor, detail of column/beam connection
NY-267-43	Third floor, detail of beam/exterior wall connection
NY-267-44	Third floor, northwest stair (former driver's stair), typical detail of all stairs
NY-267-45	Second floor, looking north at former clerical area
NY-267-46	Second floor, looking southwest in former bookkeeping room
NY-267-47	Second floor, looking south in office corridor

**Index to Photographs  
Sheffield Farms Milk Plant  
HAER No. NY-267 (Page 4)**


<b>NY-267-48</b>	<b>Second floor, looking southwest (possibly former multi-purpose room) with fire stair in center</b>
<b>NY-267-49</b>	<b>Second floor, southeast stair (former office and visitor stair), transition of marble to wrought iron</b>
<b>NY-267-50</b>	<b>Ground floor, looking northwest at former location of ground floor (bottom) level of milk room</b>
<b>NY-267-51</b>	<b>Ground floor, southeast corner, looking southeast at mezzanine (original function unknown)</b>
<b>NY-267-52</b>	<b>Ground floor, northeast corner, looking northeast at former delivery entries (archways have since been filled in)</b>
<b>NY-267-53</b>	<b>Ground floor, looking northeast at former delivery dock on Webster Avenue</b>
<b>NY-267-54</b>	<b>Basement, looking north up 1951 ramp</b>
<b>NY-267-55</b>	<b>Basement, looking southeast from ramp</b>

HAER, NY, 3-BRONX, 16-




[illegible]

Key to Photographs  
 Sheffield Farms Milk Plant  
 HAER No. NY-267 (Page 7)



Key to Photographs  
 Sheffield Farms Milk Plant  
 HAER No. NY-267 (Page 8)







Key to Photographs  
 Sheffield Farms Milk Plant  
 HAER No. NY-267 (Page 10)

